





# CP1411B3-FS



# CP1411B3-FS



A x8  
Spec:  $\phi 10 \times L40$



B x4  
Spec:  $\phi 7 \times L30$



C x4  
Spec:  $\phi 15 \times H12$



D x4  
Spec: M8  $\times$  95




E x4  
Spec:



F x4  
Spec:  $\phi 38$



G x20  
Spec:  $\phi 8 \times \phi 18$




H x1  
Spec: 5#



I x4  
Spec: M8



J x16  
Spec: M6  $\times$  45




K x1  
Spec: 14MM




L x1  
Spec: 10g



M x4  
Spec: H205





N x4  
Spec: 5/16  $\times$  L60



1

2





3

4

