















C151A ASSEMBLY INSTRUCTION (P₁¹)







①













②



 USING TOOLS	
Description	specification
A 	ø15
B 	ø8*40
C 	
D 	M8*85
E 	M6*20
F 	M6*70
G 	M6*25
H 	M8*80
I 	M6*35
N 	M8*20
O 	M8*45

C151A ASSEMBLY INSTRUCTION (P₂)



 USING TOOLS	
Description	specification
A 	ø15
B 	ø8*40
C 	
D 	M8*85
E 	M6*20
F 	M6*70
G 	M6*25
H 	M8*80
I 	M6*35
N 	M8*20
O 	M8*45