

















X-15CG




MODREST

STEP 1



A  5PCS	B  1PC
C  1PC	D  1PC
E  1PC	F  1PC
G  1PC	H  2PCS
I  1PC	J  M6*35/3PCS
K  M8/3PCS	L  8*22*1.5MM/3PCS
M  6*15*1MM/6PCS	N  M5/1PC
O  M6*40/6PCS	


STEP 2






MODREST

STEP 3





STEP 4





MODREST

STEP5



FINISH

