



# MD510 Assembly Instructions

## Parts



① x1



② x1

③ x4 M8\*25-3/5"



④ x4  
M8\* $\phi$ 16\*2




⑤ x4 M8



⑥ x1 M14



1:



2:

