



K8700

①

The diagram shows a perspective view of a rectangular plate with four fasteners. A circular callout provides a detailed view of one fastener, which consists of a top flange (A), a middle flange (B), a spring (C), and a base flange.

[illegible][illegible]